

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

-- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.


The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

-- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.



VOLUME XVIII . NUMBER 4 . MARCH/APRIL 2000



Dear Members: After sending out over 100 renewal reminder letters in January, I'm happy to report our paying membership now stands at 600. Thirty more members and we'll be tied with last

year's membership.

Two of our San Francisco members own 1938 Special Sedans Model 41. They got together and took this photograph of their 38-41's with the Golden Gate Bridge in the background.

The black one on the left belongs to **Paul DeLucchi** (#1246). The maroon car on the right belongs to **Mark Jordan** (#1297) and was featured on the back cover of the last **Torque Tube**.

The next two photos show a brown 1937 Spe-

cial 4-Door Slant-Back Sedan Model 47 belonging to **Ray Shanahan** (#1429) in San Rafael, CA. Page two shows the cars 1936 style steering wheel without the horn ring. I have seen this on

many 1937 Buicks.

Our last issue of the Torque Tube showed Albert Fink's (#941) 1938 Limited with a bar in the back of the front seat. Now Cecil Don (#637) reports that he owned a '37 Limited with a bar nearly

identical to the one in the 1938 Limited. So even though I have never seen it advertised, it appears likely Buick did offer this option on their Limiteds.

The **Torque Tube** is continually looking for interesting material to pass on to the membership.





Here are some 37/38 Buick auction items seen on the eBay Web Site. (The eBay URL is: http://www.ebay.com).

A. Original 1937 Buick sales plaque. Plaque is shield shape measuring 9 1/2" wide x 13" high. Has three metal badges attached. Top one reads "Zone average price

class or better season of 1937 through June" and has old Buick logo. Center one reads "Presented by Buick to H. R. Ingalls Inc." Bottom one reads "27.3%." A rare 1930's Buick piece in excellent condition. Price starts at \$35.

B. You are bidding on a 11 x 14 paper award certificate...to (E. A. Talbert) having delivered 75 units during the current year is a member in good standing with a rating of "Royal Purple Salesmaster"...date of award 1938...this certificate was titled "Buick Salesmaster & Royal Purple Salesmaster Club"...there is a 1" tear on right side in the border...lays flat and doesn't show if framed, this award is unframed...color of award is basically beige with some green in border and red emblem at top. Price starts at \$22.

C. Good Delco generator and four-pronged voltage regulator for 1938 Buick Special. Price starts at \$25.



D. Original New Old Stock 4-prong voltage regulator for 1937 and 1938 Buick Special straight eights. Part number 1118213. In original Delco-Remy box with original instructions. Very hard to find. Price starts at \$25.

E. Very nice Tootsietov 1938 Buick Roadster.

Near mint condition. Marked Tootsietoy Made in USA. Measures 4.25". Price starts at \$1.00

F. Buick 1938 Hood Ornament, INF 1298513 1298515 — 13" long. No pitting, no damages, excellent Hood ornament like new. Price starts at \$40.

G. 1938 Buick Instruction Manual in French. This 1938 Buick manual is printed in the French language but with the accompanying pictures it shouldn't be too hard to understand (maybe this gives you the opportunity to learn French). The manual is complete and in fair to good condition. The outside is a bit dirty but it is not ripped or otherwise torn. Price starts at \$10.

Thanks to Charles Jekofsky (#514) in Washington, DC for sharing this information.

Club member Jim Ishmeal (#1475) recently purchased this 1937 Century Sedan Model 61. It's painted black which is its original color. lim

You can now find your '37-'38 Buick Club on the World Wide Web: http://www.classicar.com/clubs/buick/buick.htm

The TORQUE TUBE is published every two months for the enjoyment of the 1937-1938 Buick Club. Membership dues are \$34.00 per year US, \$35.00 per year Canada or Mexico and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the 1937-1938 Buick Club.

Please send all articles, ads subscriptions and inquires, etc. to:

The TORQUE TUBE 1005 RILMA LANE LOS ALTOS, CA 94022 USA

Editor:.....Harry Logan, #651 Art Director:.....Dug Waggoner, #10

You can reach Harry Logan by PHONE/FAX (650) 941-4587 or by E-mail: harrylogan@earthlink.net

Printer Liaison: Bill Olson, #427 Printer:.....Conrads Printing, Lancaster, Ohio All rights reserved. No part of this newsletter may be reproduced in any form without written permission from THE TORQUE TUBE

says: "It's a honest "6" on a scale from 1 to 10. I want to phase restoration of the car so as not to have it down for long periods of time. I enjoy driving it and it really turns heads as she

glides down the road. As the plates show, I bought it in Minnesota. It's now a resident of the High Desert in Victorville, CA."

Club member Peter Warburton (#1163) in Australia writes about sending US dollar checks from Australia: "I found Australia Post pro-

vides a Western Union International money order. This has proved to be much cheaper than a bank draft." Perhaps this might benefit our other overseas members

The cartoon and thatched roof English gas station appeared in a 1940 issue of Motor Age magazine. Under the thatched roof was a

modern service station in Devon, England.

"I don't like to bother you,

but I'm just curious

The cover of the February, 1998 Radio Control Modeler magazine (at right) shows off a 1938 Buick as well as a 1934 Packard. Also note the very nicely constructed "Golden Era" model aircraft. The picture was taken in Adelaide, Australia in 1997. There is no mention as to the owner of the cars but the women on the right is Claire O'Reilly. Perhaps she is a member of one of the Australian Buick Clubs. Thanks to Dick Parkes (#169) in Canada for sharing this.

In 1937, an auto parts company in St. Paul, MN introduced this Oilometer-Gear Shift knob (middle of page 4). You set it to indicate the mileage at which lubrication is desired. The meter fits in the shift ball and indicates the mileage the





car should be returned to the dealer for oil changing or lubrication. eliminates the necessity of attaching tags to the car, and serves as a guide to remind the owner of lubrication peri-

ods. List price is \$1.25.

The next two photos on page 4 were part of a History Channel 3 hour color video called "World War II in Color." The photos were taken in France shortly after the German invasion in May, 1940. One scene shows a black 1939 Buick flying a Nazi banner with

big army trucks and a very old church in the background. In another scene we can





sidemounted '39 Buick with a dead

man in the foreground. I Oilometer Combined would like to know the story behind this scene. How and why was the man killed. He appears to be in civilian clothes and what looks like wooden shoes. Unfortunately he was just one of the over 50,000,000 people killed in World War II.

One of our newest Club members Kenneth March (#1481) of Thomasville, PA owns this 1938 Special 4-Door Sedan Model 41. Notice his car (bottom of page 4) has the original glass which is fogged about half-way up the windshield. By looking at the small LOF (Libby-Owens-Ford)

In Gear Shift Ball

The Robinson Co., First National Arcade, St. Paul, Minn., has introduced a combination gear shift ball and meter that can be set to indicate seriods at which lubrication is deperiods at which lubrication is deperiod. The meter is fitted into the gear shift ball, and indicates the milesges at which the car should be resage at which the car should be




turned to the dealer for oil changing or lubricating. It eliminates the necessity of attaching tags to the car, and serves as a guide to remind the serves as a guide to periods. List owner of lubrication periods. price, \$1.25.

Jenkins (#1085) in North Carolina. Thanks to Gene Stewart (#1456) for sharing this photo at the top of page 5.

This next picturesque photo shows a Sudan (light) blue '37 sedan belonging to new member Jim Markowitz (#1488) in Bridgeville. PA. Jim recently acquired this car in Pittsburgh, PA. Jim is the car's third owner.

John Wilson (#1406), our only member from the state of West Virginia, owns two 1938 Specials, a coupe and a sedan. John can't drive them now because he is living and working at the South Pole. You can fly to the South Pole from New Zealand when the weather is good i.e. in sum-

mertime below the Equator (Nov/Dec/Jan).



logo with manufacturing date at the bottom cor-

ners of the windshield, you can get an idea when your car was built. My 38 sedan glass is dated 10/37 and 11/37 so my car was probably made in December 1937.

This beautifully restored twotone 1932 Buick convertible coupe with rumble seats and sidemounts belongs to Lewis

While in New Zealand, John had a good visit with



Greg McKenzie (#1215). Greg also had a 38 Special sedan which he recently sold. John says the weather is running 40 to 50 degrees Fahrenheit below zero. But it doesn't feel too bad except on your hands with your gloves off.

In finding services that restore or rebuild body parts I've found that the best place to have your

running boards re-done is with Hunley Acuff, 1423 Wilson Road in Rossville, Georgia 30741. His phone number is (706) 866-4875. Call between 7 and 9 pm or the phone may go unanswered.

The Buick Farm

This Venezuelan stamp showing a 1937 Buick

4-door convertible was sent in by José Pardo (#558) in Colombia, South America. José has been involved full-time in the founding and construction of the National Museum of Transport in Cali, Colombia. All 5 of his '37





Metro de Caracas 1981

sells only NOS parts
that the owner acquired years ago from
various Buick dealers.
Instead of phoning
and asking if he has
the part you need, go
to his website
(www.buickfarm.com),
enter the year of your
Buick and get a list of
parts in order by Group

Number. You can print out this list for future reference or order the parts on-line. Buicks are in the museum. José likes 1937 because it's the year he was born. The museum also features his W.W.II AT6 Texan trainer airplane.

Andrei Bogomolov in Moscow, Russia has a gallery of antique Buick cars on the Internet. The

URL of his '37 and '38 Buick

websites are:

http://www.autogallery.org.ru/bui1937.htm http://www.autogallery.org.ru/bui1938.htm Andrei writes in good English. He says the Kremlin garage had some Buicks, mostly limousines. Some are still scattered around Russia. A list of antique cars in Russia for sale is also on his web site. I wonder where all those old prewar BMW's and Mercedes came from? If you're interested, you can write Andrei at: ab@iki.rssi.ru



This 1937 Business Coupe, above, belongs to member **Christian Stickle** (#1313) in Tübingen, Germany, an old University town. Christian recently purchased a pair of original jump seats to

install in has coupe for his child to ride on. That will change the car from a Business Coupe to a Sport Coupe. The photos were taken last Fall. What a beautiful castle and car. And no, the castle is not Christian's home.

These three photos show a

handmade model of a 1938 beige coupe. It is now for sale along with the maroon or blue 4door sedan

shown on page 6 of the September/October 1999 issue. They are very detailed and handmade in France in small batches. They cost \$125.00 plus shipping. They accept payment with a credit card. If you're interested, contact:

Ray Paszkiewicz Jr. PO Box 156 , Clarksburg, NJ 08510 Tel: (732) 446-9381 Ray says he will do a '38 Convertible Coupe soon. I'll let our members know when it's available. Also see his new ad on page 30 of this issue.

This beautiful blue '38 Century Sedan Model

61 (top of page 7) belongs to José Ramon Garcia Menendez (#856) in Argentina His car appeared on the front and back covers of Vol. X, No. 5 (March, 1992) with an attractive blonde by the name of Sandra. José reports that unfortunately for him,



Sandra is now living near Los Angeles and is one of the three stars in a remake of the Charlie's Angels TV series. José recently renewed his subscription because: "I miss the Torque Tube and the stories from the wonderful group of the friends of 37/38 Buicks."

New member **Dan Lash** (#1468) in Michigan owns a 1937 Special McLaughlin-Buick con-



vertible coupe. All the 37/38 open cars were Flint built. Dan's was also. It has the US Data Plate, not the Canadian one. His plate reads:

BUICK MOTOR CO.

FLINT, MICH.

STYLE No. 37-4467


BODY No. 1647

TRIM No. 343 (Tan Bedford Cord)
PAINT No. 508 (Samarra Beige)

His car has 6 lug wheels and different hubcaps than US '37 Buicks which indicates the car was shipped from Flint to Oshwa, Canada where McLaughlin wheels were installed.

The original Hebrew Hotrod! This Buick ad (above, right) appeared in the Jewish Forward newspaper on July 5, 1937. It is written in Yiddish with Hebrew letters. People who can read Hebrew will have to convert the words to Yiddish, a form of high German. Obviously, Buick was targeting all the markets they could reach. Thanks to Charles Jekofsky (#524) in Washington, DC for sharing this ad.





ITS NEVER TOO LATE

TO LEARN THIS!

- Rear Axle Ring and Pinion Gear Set (44:11)

 Part no. 1394389
- · Rear Brake Drum Part no. 1293550
- Front Brake DrumHub Part no. 1289611
- Delco Front Shock Absorber

Right 1902-D 58 Left 1902-C 58

 Delco-RemyStarter Vacuum Switch Part no. 1868512

If you can help, please contact **Jari Vuorinen** at: Mantypolku 5

47710 Jaala

FINLAND

E-mail: perhe@iobox.fi

FAX +358 5 3634 508


Fally

(Cover Cars)


Front cover: 1938 Century Pick-up Truck. This photo was taken in 1978 shortly after then owner Lee Greer finished restoring it. Lee said it was a beauty and drove and handled like a '38 Century should. Rear cover: The1938 Century Pick-up today. It's now owned by George Belanger (#1486) in Winthrop Harbor, Illinois. See story below.

O 1938 CENTRUY PICKUP TRUCK

By Bob Trueax (#351)-Gridley, CA



A photo of this beige 1938 Century Pick-up truck appeared in the January 20, 2000 issue of Old Cars Weekly. The new owner, *George Belanger* (#1487) of Winthrop Harbor, IL was inquiring if anyone had information about its history. I first became aware of this vehicle around 1974 when it was purchased from a man in Carson City, NV. It was in poor shape with a cracked steering wheel, no taillights and the dashboard was painted red with a brush. I trailered it from Carson City to Oakland, CA. for the new owner.



The unverified story that came with the car

brought sad memories to the Howard family.

was that it was built by Howard Buick (one of the largest and oldest Buick dealerships in CA) out of a 1938 Century Sedan Model 61. It was built for Mr. Howard to pull a trailer transporting his race horse "Sea Biscuit." When that horse was killed in a barn fire in 1947, the Buick pickup was sold as it

had it, so really don't have anything on the history for the next 25 years.

The car was sold to Lee Greer around 1975. He took care of the restoration. He bought a '39 Century engine from me. That engine had been rebuilt but never run. Lee and I disassemble, cleaned, reassemble



and installed it in the truck.

I don't know how long the fellow in Nevada



Everything was re-done as originally customized, except that the back of the cab was finished off better, wooden side-boards were added to the oak bed and it was re-upholstered with brown leather. Lee also added the missing taillights and had the steering wheel and woodgraining redone. He did a nice job with the vehicle, entered it in some shows and sold it in 1977 to well-known car collector/dealer Bob Adams in Wisconsin. Then it spent about ten years in a car museum in Evanston, IL. It ended up in Racine, WI. where the present owner George Belanger purchased it. I always though it was a neat vehicle and hated to see it leave California.

TRAVELIN' MAN

By Harry Logan (#651)-Los Altos, CA

Von Hardesty (#964) of Arlington, VA. recently visited the Moscow Polytechnic Museum in Russia. They have a large antique car collec-

tion stored in a Cold War underground shelter! The Soviets manufactured Fords under license. Von is standing next to a Russo-Balt, one of Russia's first autos.

In the middle photo shows two 1937 Convertibles. That's Von's maroon'37 Century convertible coupe on the left and Andy Diem's (#852) dark green '37 Special Convertible Sedan on the right at a show in the Wash-

ington, DC area. Von also has a 1940 Ford Convertible Coupe.

Von also owns a 1940 Nash 4-Door Sedan, the same year and model Nash his father had. His Nash was recently featured in an article in the Washington (DC) Times newspaper.










1937-1938 BUICK CLUB **EASTERN MEET AND TOUR**

RED WING, MINNESOTA JUNE 6-7-8-9, 2000

Dave Wettersten (#887) - Falcon Heights, MN - Tour Leader

Red Wing, in southeastern Minnesota, is a lovely, historic community situated along the Mississippi River the heart of the Mississippi Valley. Surrounded by bluffs it is well known for its natural beauty. Our host hotel, the St. James, is on the National Register of Historic Places and features an





We will be touring the Great River Road loop along a scenic drive of the Hiawatha Valley following both the Minnesota and Wisconsin sides of the Mississippi river. We will also be touring along the St. Croix river to Stillwater, Minnesota, a river valley and town equally as pretty as the Hiawatha and Red Wing.

#Attending

For those interested in independent excursions, Red Wing is about an hour (in a modern car) from St. Paul/Minneapolis and the Mall of America. However, both Red Wing and Stillwater provide ample opportunity for shopping. For golfers, there are links nearby. You might consider staying an extra day to take a ride on a paddlewheel boat like the Mississippi Queen down the Mississippi River. Dave and Carolyn Wettersten will arrive Tuesday afternoon.

— — — — (please copy and return this completed form) — — — —

2000 EASTERN MEET REGISTRATION

Address City____Zip___ Tour Car Year/Model Meet Registration Fee - \$12.00/Car (hospitality room, etc.) · Wednesday 6/7 Tour #Attending •Thursday 6/8 Tour #Attending Friday 6/9 Tour #Attending · Friday 6/9 Dinner (Cost will depend on order)

Make Checks Payable To:

David Wettersten

1724 Asbury Street • Falcon Heights • MN 55113-6250 • Phone (651) 644-1019


HOST HOTEL

St. JAMES HOTEL, 406 Main Street, Red Wing, MN 55066 . Phone 1-800-252-1875 or (651) 388-2846 Make reservations direct with the hotel, and don't forget to mention the 37-38 Buick Club to get this Special Rate: \$86 + tax - 20 rooms are being held until May 8.

Name_

"A MYSTERY SOLVED"

By: Clarence Hoffman (#546)-Pennsylvania



s some of you know, I bought a 37-46C a few years ago. This photo shows me riding in the rumble seat of another 37-46C. My car had supposedly been professionally restored some 16 years prior to my purchasing it. The fellow that had the car restored died before he had a chance to even use it. His business partner out, of nostalgia for his friend, bought it from his estate and it was he that I bought the car from. I asked him about the cars past and restoration but he couldn't tell me anything except his partner had spent quite a lot to have it restored. A word to the wise here, all restorations are not equal.

So after years of work I drove my car to the 37/38 Eastern meet in Indiana last May. I'm not going to bend your ear with my many problems, instead I feel you would much rather read about the great mystery I solved in my efforts to properly restore this car to it's former glory.

In trying to right one of the many wrongs in the car's restoration, I had to remove the rubber mat in the small trunk beneath the rumble seat. Surprisingly enough the condition of the mat seemed to indicate it was in fact the original. Water had been leaking into the trunk due to the fact that the two drain tubes had never been properly installed. I fixed them and removed the mat in order to sand some of the surface rust from the floor of the trunk. After looking carefully at the area beneath the mat I noticed what

looked like the remains of an official looking document. I was intrigued by what I might find on this typewritten document or rather what was left of it. Stuck to the floor of the trunk was about one-third of the upper left-hand corner of a letter.

It was facing toward the rear and with the limited amount of space to stick my head in, I had to use a small mirror to reflect the typewritten words. Well as you can imagine it was very hard to decipher as all the words were backwards in the mirror. I struggled with the words for about 25 minutes and had only managed to figure out about four words. I thought, "the hell with this" as I'm not getting anything done on the car, which was what I had come out to do, when I realized the name I had just managed to figure out was Frank Knox, Secretary of the Navy back in 1937. What I could make out of the date, it appeared to have been sent on April 1st, 1937. I got enthused again and thought maybe the rest of this letter is stuck to the back of the mat. I flipped the mat over and sure enough about half of the letter was still stuck there. The only problem being I was looking at the back of the letter now. I could never get what was left of it off the mat without destroying it. I called my brother who teaches computers at a High School and told him about my letter. He said he had a friend who had a computer that might be able to pick out the typed words pressed into the paper from the back and to bring the mat over and he would see what he could do. Three nights later he called to say his friend had some success, from what he was able to get it went something like this:

We are sure you can _____ time frame _____ both you and Noonan ____ transform_ers sh_ld help wish you ___ Fred every ___ cess.
Fra__ Kn_x, Sec. N_vy.

y brother being 10 years younger than me asked if it made any sense to me. I told him that along with what I was able to get, it seemed to make a great deal of sense. I said I needed to find out, if possible, the original owner of the car. I could then be more certain of my suspicions. According to the fellow I bought the car from, he thought his business partner had claimed to be the third owner. So I began to try and find the original owner, beginning with his partner's title transfer and working back. I was finally able to trace it back to the original owner. It was purchased on December 7th, 1936 from Phil Hall Buick in Hollywood, CA by a Mr. George Putnam for his wife. I was disappointed at first until I remembered that George Putnam of Putnam Publishing Company was in fact married to Amelia Earhart. I can tell you my heart was really racing upon discovering this. I called my brother and told him I was sure that the car had belonged to Amelia Earhart and that the letter proved she and Fred Noonan had indeed been on a secret mission for the Secretary of the Navy, Frank Knox.

My brother told me I was nuts and to come and get my mat back and "get a life". I had just bought six new Wide Whites for the trip to Indiana. I removed the tires and tubes from the side mounts; they looked like the original equipment. Upon removing the tubes, I noticed a large hot patch 3 square inches on each inner tube. When I dropped the first inner tube on the floor it went clunk! Inner tubes don't usually clunk when you drop them. I shook the tube and sure enough there was something inside. I cut the old tube open and found a stainless steel ball approximately the size of a golf ball. I shook it and there was indeed something inside that whirled around and made the ball feel like a gyroscope. I cut the

other tube open and there was a stainless steel ball in that tube as well. Try as I might, I could come up with no explanation for the two steel balls in the tires.

About two miles straight down the dirt road that I live on is a friend who teaches mechanical engineering at the local college. He is also a ham radio operator and collects antique radios among other things. I took the steel balls to him and asked him to see if he could figure out what they were doing in the sidemount wheels. Two days later he thought he had figured out what the two steel balls were for and could I come over, he wanted to show me something. I said I'll be right there. When I got there he explained that he had been using his ham radio set just flipping frequencies. When he hit 122.5 he had on his head set and said that he suddenly received an SOS signal dots and dashes so loud he had to pull off his head set. He said he couldn't figure out where the signal was coming from. When he happened to look over, he found his five year old son Mike rolling one of the steel balls across the basement floor next to him! He said he and another ham operator friend checked them out. They were indeed small emergency transmitters. When rolled, the inner ball sent out an SOS signal with dots and dashes.

Te talked it over and came to the conclusion that the mechanical transmitters were to be a back up on Amelia's round the world flight. They had obviously been tested on the car to see if they worked properly before installing them on her plane. Had someone forgotten to remove them from the car and install them in her plane's landing gear? The Lockheed Electra that Amelia flew had retractable landing gear. What I and my friend theorize is that were she and her navigator Fred Noonan to lose electrical power to the radios they could lower the landing gear, thus causing the wheels to spin activating the transmitters inside of the tires. I have told no one else of this story. Now that you my fellow members of the 37'/38' Club have read this, I think I can safely say, we of the 37'/38' Buick Club may be the only people who really know the answer to what happened to Amelia Earhart. Oh yes, I know there are some skeptics out there saying I know Hoffman, and he ain't got no balls! Well I can assure you my friends I do!!

My grandmother Ellen Moll bought this 1938 Buick Limited Model 90L in 1939. She was told it had been chauffeur driven and owned by a New York City Park Avenue widow.

However from 1939 on, my grandmother was the only "chauffeur." She drove this as the family car. I suppose that with all its seating, it was


With family in both New Jersey and Florida, the car made many trips

up and down the East coast. Many times I've heard my mother and grandmother laughing and remembering different mishaps and adventures in the car.

My grandmother once fell out of the car. My grandfather didn't

notice until my mother piped up that Mama was missing. You can imagine the panic that followed.

Some years ago my sister and I ended up in Minnesota with our families. Nearly 2 years ago, my mother retired and joined us up here. Last April my grandmother, now 93 years old, moved into a nearby retirement center. We are all so pleased that the car will still be close to her.




By Jan Burry (#1477) - Northfield, MN




The photo shows the car with non-original wheels. We have the originals and will put them on. The interior needs some re-upholstery but the body is in good shape. The car was garaged in Tampa, Florida for 50 years.

WITHERING




sidemounted Limited Limousine. The list of his cars for sale was sent in February to several car clubs including the Nash Car Club.

Bob Hamro (#775) - San Jose, CA is shown looking in the trunk. It contains a 38 transmission and also an 8 inch (20 cm) hole. The trunk lid is missing the chrome hinges. It's held on by electrical wire.





The interior of this 1938 Limited Model 90L was filled with car parts, but not all from this car.



Notice the X stamped on the bottom right corner of the firewall data plate, indicating this car was exported, probably to Mexico and then later returned to the US. This 90L was originally painted (#515) black with (#634) Gray Broadcloth upholstery. It has Body No. 116 out of a total of 577 (167 of these were exported). Frank was asking \$6500 for this car! By the time you read this, these cars will have found a new owner or been crushed.

Paul DeLucchi (#1246) visited these cars. Here are his comments:

"I spent a while poring through the boxes and poking around the hulks. What an astonishing array of stuff, from NOS taillight lenses in Buick boxes ('50s) to that enormous 38-90L. It has ONE wire wheel? I wish I had the wherewithal and the balls to take on a project like that!

Other odd observations: Some "KUICK" hubcaps for 40s Buicks, in the same barrel with the real ones. A trunk lid for a Hudson Hornet complete with both emblems.

Buick doors stacked up like books on a shelf. And that LaSalle hearse — too far gone for a showcar restoration, but wouldn't it make a great custom job, or a starting point for a woody? And I'm sure you noticed the complete front clip from a 38 Special — with a decent radiator in it — just sitting out in the mud. Oy!

In my opinion, the sleeper of the entire lot was the '46 Nash coupe, a humble car but original and complete from end to end, with upholstery still serviceable and someone even took the care to lock the doors. Frank says it runs but brakes are no good. Asking \$2500 and he'd probably take \$1900. It would be an easy fixer-upper on a budget, and a cutie besides."



FUEL PUMP INFORMATION


By Harry Logan (#651)-Los Altos, CA

(Note: I obtained most of this information from fuel/water pump rebuilder Arthur Gould in NY).

A particularly distressing situation occurs when we replace a fuel pump with a "New Old Stock" (NOS) one that we'd been counting on, and find that it works, but the diaphragm leaks live a sieve.

The old pre-war (and several post-war years) fuel pumps had diaphragms constructed of layers of a cloth-like material, impregnated with a gasoline-resistant material. These are no good now because age deteriorates the layers and modern fuels causes them to swell. So do not use any of these multi-layered diaphragms.

Later diaphragms from about 1950 up are constructed of neoprene or nylon and are virtually indestructible and are easily distinguished on the pump by looking at the edge which is only one ply (40 to 60 thousandths thick) instead of multiple ply.





The only company supplying complete fuel pump kits was Chem Manufacturing Co. and they went out of business in 1989. There are no good, complete kits on the market today.

It's folly to rebuild your fuel pump with a flea market kit. They often have incorrect parts or the kit is incomplete, often lacking the oil seal. Your best bet is to send your pump to:

Arthur Gould 6 Delores Lane Fort Salonga, NY 11768 Ph: (516) 754-5010


Arthur has rebuilt 4 fuel pumps for me and all are still working, even the one he rebuilt in 1988. He has all the parts necessary to restore your pump plus some specialized fuel pump tools. He also restores water pumps and has done an excellent job on the four I sent him.

WINDSHIELD Technical WIPER NUMBERS



By Bob Graves (#1136)-Lynn, MA

Buick (and probably other GM cars) used **Trico** windshield wiper motors, linkages, blades and arms. You can purchase reproduction Blades and Arms from Bob's Automoblia (805) 434-2963.



Below are the Trico motor and linkage numbers for our Buicks. These numbers are stamped on them. For example, this linkage number is Trico part number 77618. It's for the left (drivers side) of a 1938 40 or 60 Series car. (see table). Sometime the last letter of the part number, in this case C, was not stamped on the linkage.




	1937 40 & 60 SERIES
MOTOR	LINKAGE
SK-24	76781-C (left-driver) 76780-C (right-passenger)
	1937 80 & 90 SERIES
SS-4	76696-C (left-driver) 76696-C (right-passenger)
	1938 40 SERIES
SK-24-1	77618-C (left-driver) 77617-C (right-passenger)
	1938 60 SERIES
SK-23-1	77618-C (left-driver) 77617-C (right-passenger)
	1938 80 & 90 SERIES

77576-C (left-driver)

77577-C (right-passenger)

SS-8



The sides of 1938 Buick wiper transmissions flare out while 1937 transmissions had straight (nonflared) sides. Be sure you install the transmission parts on the correct side (left and right). If you reverse them, they will fit, but something might break when you try to use the wipers.



1937 BUICK QUESTION & ANSWER

(From the March, 1942 issue of Motor Age magazine)

Ed Smith, an auto mechanic in Sacramento, CA submitted this question to the magazine.

"We have a 1937 Buick Special, on which we

have ground the valves. renewed the rings, pins, and generally reconditioned the motor. We also have taken 1/8 (.125) inch (3.2 mm) off the head in an attempt to increase the performance and gas mileage. We have obtained about 110 pounds

cylinder pres-

sure, which is

made a carburetor exchange to the later type Stromberg, as recommended by Stromberg.

The ignition is set at pinging point, using high-test fuel. We are at a loss to understand why an improvement in both performance and gasoline mileage has not resulted. We are particularly unable to understand why even less mileage is obtained than prior to doing this work. This car has been averaging about 15 miles to the gallon on the open road before, and we have been able to equal that only by a too lean adjustment of the carburetor. Can you tell us where we have failed?"

I find it difficult to answer your question. Personally. I think the main trouble is one over which you have no control and that is the gasoline. The

government in 1942 restricted the use of tetraethyl lead and consequently the fuel you are now getting does not have as high an octane rating as quality fuel did only a few months ago.


1 am inclined to believe that if

you had not raised the compression and simply overhauled the engine, the performance and gasoline mileage would have decreased considerably. As it is, your work has resulted in maintaining the same economy and

performance as the car formerly gave with better fuel but lower compression.

There are only two things I can suggest. The first is to analyze the exhaust gas and make sure the analyzer has been recently overhauled and is


in good condition. Check the exhaust gas through the complete range of speeds. The other suggestion is to change the spark plugs. This is necessary because of the change of compression would necessitate a spark plug having a different heat range.



'38 REAR SHOCK ABSORBER CLIPS

By Paul DeLucci (#1246)-San Francisco, CA





7/8"-

2.25 cm

When installing new shock absorbers, you may have to trim the rubber bushing to get it to fit. Then you have to squeeze the rubber bushings

to get the upper clip on. I used snap rings instead of the original little crescent-moon clips. The crescent-moon clips might have worked well when they were new, but mine had lost both their shape and their springiness, and were worthless. I used a valve spring compressor, but you must first remove the upper mount that bolts to the frame.

I hunted all over for these clips without any luck. You can find the diameter and style easily, but not the thickness. And the thinner ones are no good, even doubled up (I tried).

Finally after much searching, I found this 7/8" (2.2 cm) in diameter snap ring fit perfectly. They are 5/64" or .078" thick (2 mm) and are much stronger than the original clips.

The clip is a Truarc 5160-75 retaining ring. Our members can ask for it at their nearest machine supply or bearing supply store. Truarc is a big national company. If they're out-of-stock, they can be ordered, at \$11.50 a dozen. A nuisance unless you have 6 cars. Meanwhile, I'll gladly mail a pair, free, to the next 6 mem-

bers who mail me a SASE: 470 Lombard St., San Francisco, CA 94133.

OK, it's a small thing, but I've found that the smallest things cause the biggest frustration!



I needed to replace the rear shocks on my '38 Buick and referred to the technical tip from the Nov.-Dec. Torque Tube which stated that NAPA shocks part #76992 would work. The NAPA store here in Americus, GA, said these shocks were obsolete and no longer available. They recommended an almost identical shock part # 94148. I bought a set and they fit and worked fine. However the 1 5/8" diameter washers supplied with the shocks have a 1/2" hole and will not fit the top mounting pin. A 1 5/8" washer with a 3/4" hole as well as a new snap ring will have to be aquired. I thought this would be helpful if others need new shocks.

ED: Brian Jensen in Baltimore, MD also adds: I just wanted to mention that I followed the advice for "Modern Replacements for Buick Rear Shocks"

1938 REAR SHOCKS

By Carl Lohstroh (#1098)-Georgia and Brian Jensen (#1372)-Maryland

that was in the Nov.-Dec. *Torque Tube*. The NAPA Grande' 60 gas charged shocks did fit perfectly and my '38 Buick does indeed ride so much better.... Thanks for the tip! However, you might want to pass on to other club members that these shocks are on the NAPA obsolete list and when stocks are used up they will no longer be available (according to my salesman).

They had to be special ordered from the few remaining in my area and the two shocks came from different warehouses. They even had a difference in color; one cream, the other white, (I painted them both black to match and to be less noticeble!) They apparently fit older trucks such as a 1967-'71 Ford motorhome, etc. so, I can see the less demand for them. My advice...Get 'em while you can!!!

DON'T LET YOUR BUICK TAKE IT ON THE CHIN

INSTALL these rugged safeguards front and rear and save many times their cost in locked bumpers, crushed grilles, and dented fenders. Designed especially for Buick, these handsome accessories offer double insurance for the beauty of your car. Not only do they protect the sleek front and rear lines from unsightly bumps and scratches but they also add that final, finished touchin a way that makes an integral part of the car lines.



De luxe grille guard...(above) Extra-strong insurance against bumps and locked bumpers is provided by this deluxe grille guard. Stamped from heavest steel and plated with handsome nickel-chrome finish, this sturdy, tubular guard will withstand the heaviest bump. Centered upon the front bumper, it blends perfectly with the twin bumper guards and other fittings. Price \$2.95.



Regular grille guard... Designed to match the bumper guards perfectly, this strong grill guard extends seven inches above the bumper bar, gives protection to the expensive radiator grille and center strip, and prevents interlocking of bumpers with subsequent damage to fenders. Price \$1.95.

Rear center guard...Protection to compartment lid, lamp and handle is the duty of this handsome, nickel-chrome plated rear center guard. It will fold back out of the way to allow easy access to the rear luggage compartment or spare tire space. Harmonizes with rear bumper guards. Price \$2.95.



Rod Davis Sr. (#1485) 34379 Orange St. Wildomar, CA 92595 37-81

Gabriel Rossetti (#1486) 1290 Nipomo Ave. Los Osos, CA 93402 37-41

George Belanger (#1487) PO Box 256 Winthrop Harbor, IL 60096 38 Century Pick-up Truck

Steven Hartwich (#1488) 8240 Summit Kansas City, MO 64114

Jim Markowitz (#1489) 1300 Enfield Court Bridgeville, PA 15017 37-41

Tom McGree (#1490) 1919 Highland St. Helena, MT 59601 38-48

New Members

Sverre Christoffersen (#1491) Nesalleen 30 N-3124 Tonsberg NORWAY 38-61

Ronald Garcia Sr. (#1492) 15 Manor Court Manalapan, NJ 07726

Jari Vuorinen (#1493) Mantypolku 5 47710 Jaala FINLAND 38-81



Voss Motor, Inc. (#1494) 21849 Virginia Dr. Southfield, MI 48076

George Girot (#1495) 560 Stapp Road Boulder Creek, CA 95006 38-46C

Sherry Bargar (#1496) 5244 Folsomville-Degonia Rd. Tennyson, IN 47637

John Welby (#1497) 1665 Shipman Rd. Oxford, MI 48371

Nigel Leedham (#1498) 423 Madison St. Coquitlam, BC Canada 37-81 McL

> Glenn Blackmore (#1499) 1040 Meadowbrook Dr Troy, MO 63379

Parts FOR SALE

SIDEMOUNT COVERS - PLUS

I have a full set of Buick Roadmaster spare tire covers for side mounts in very good shape (no stainless) all pieces. And I also have various odds and ends for '36,'37, and '38 Buicks.

Ray Helger

E-mail: rayh@wsii.com

1938 PARTS

Plus Shipping

Butch Leonard (#1257) 62777 Erickson Road Bend, OR 97701

Phone: (541) 382-5202

• 1937 & 1938 NOS* PARTS					
1937-40 Second and third speed sliding sleeve	\$25				
1937-1938 all, transmission main drive bearing					
1937-1938 40-60 Outside door handle, non-locking, used					
(marked H30087 or H322553)	\$10 each				
1937-1938 40-60 Outside door handle, non-locking, used					
(marked H17712 or H33912 or H30075)	\$10 each				
1937 40-60 Locking door handle, less lock, 1st type					
with offset shank, #4074570, marked T19500	\$35 each				
1938 40-60 locking door handle, less lock, #4089306, marked T19541					
1938 right taillamp door, used					
1038-40 after engine #4-3445305 rocker arm assembly, used					
1937-1938 all, generator armature					
*All parts are NOS except where noted. Add 15% for postage.					
Bob Graves (#1136)					
56 Dartmouth St.					
Lynn, MA 01904					
Phone (eves): (781) 593-9534					
• 1938 PARTS					
1937 original hubcaps, fair to good condition	\$100 cat of four				
Large Series Spark plug cover, very nice					
Master cylinder body and parts. Rebuildable	\$40				
Steve Nathanson (#656)					
Walnut Creek, CA					
Phone (925) 947-6711					
E-mail: my37buick@aol.com					
• 1937 PARTS					
Parting out a 1937 Buick Century 4-Door Trunk-back Sedan Model 61.					
Sidemounts with covers. Complete	61 700				
Plus many other parts. Please call.					
Emile Langlois (#1184)					
93 Edgewood Ave.					
Havershill, MA 01832					
(978) 372-2585					
• VARIOUS PARTS					
Rebuilt Stromberg carburetors:					
• AA-1					
• AA-2					
Front license plate holder					
10 small series head gaskets					
Complet collection of Torque Tubes \$750 for	all plus postage				
Mike Hart (#677)	an plus postage				
186 Brushy Plain Rd.					
186 Brushy Plain Rd. Branford, CT 06405-2601					

Parting 1937 and 1938 Buicks. The following is just a portion of what's available. Call with your needs.

'arting 1937 and 1938 Buicks. The Jollowing is just a portion of what's available	. Call with your needs.
1937 PARTS	\$2,000
Century sidemount fenders and covers, complete	\$200
Coupe and Convertible coupe left taillight, complete	
Coupe rear fenders	
Coupe trunk lid	
Special Stromberg AA-1 complete	
40 & 60 Series gas tank	
80 & 90 Cowl stainless	
40/60 Series rear brake cables, good condition	
Master and deluxe heaters	
Century brake & clutch pedal assembly	
Century radiator	
Special radiator	
Rear springs 40 & 60, good condition	\$100 pair
Radio delete plates	
Small series throttle linkage	
Big Series rocker assemblies	
Fender lights	\$65 pair
Trunk lights, complete	\$50
Tail lights with lenses, all series	\$50 pair
Wiper transmissions	\$50 pair
Special manifold	\$75
Throttle cable	
Special transmission	
Special splash pans	\$40 pair
Century hood	
Headlight switch	
Radio grilles	\$15
Wiper motors	\$15
Trunk hold-up arms	\$20
Sun visors	
Bumpers	\$40 each
Bumper arms	
Steering wheel	\$50
40 & 60 running board brackets	550 set
Buick creast badge for hood trim strip	50
Gas pedal	\$15
Small and large series generators	\$75
Large Series AA-2 carburetor, complete	\$250
Instrument cluster with working temp. gauge	\$100
1938 PARTS	
40 & 60 Series gas tank	\$150
NORS rear break cable, 40 & 60 series	\$50
Fender lights	\$100 pair
Limited left visor	\$25
Glovebox clock hole filler	\$15
Limited door sills	\$75 set of four
Breather tubes	\$10 each
Irunk hold-up arms	\$20
734Z starter with solenoid	\$50
Horn button	\$10
Special hood lettering	\$20 pair
(this Par	rts Ad continued on page 26)

(Parts For Sale continued from page 25)
Defroster ducts
Wiper transmissions\$50 pair
Rear license plate stand, bracket & light for sedan
Tail lights, complete\$75 pair
Assist straps with screws
Throttle cable
Special radiator
Battery tray 520
Generator
Special manifold, complete
Special hood sides & tops\$25 each
Grille, no cracks, minor pitting\$200
Century radiator\$100
Rear muffler hanger, NOS
• 1937 & 1938 PARTS
Century running boards, solid cores
Restored nose stainless\$200
Limited dome lights
Limited dome lights
Large series sidemount cups
Big Series spark plug cover
Special running boards, solid cores
Headlight buckets\$20 each
Large Series air cleaner\$75
Large series fan belts, new\$15
Map light switches
Small series spark plug covers\$40
Rear fender splash aprons\$15 each
Big Series manifold ends\$50
16" beauty rings \$10 each
Headlight bezels\$20 each
Trunk hinges
Front arm rests \$25 pair
40 & 60 rear vent windows, need plating\$50 pair
Rear view mirrors\$15
Special rear motor mounts \$15
Century rear motor mounts
40 & 60 4 dr. sedan doors \$75 each
Front vent window frames & mechanisms
Big Series fuel pump cores\$50
Keyed ignition switches
4-Post voltage regulator, used\$25
15 Beauty rings \$10 each
Headlight adjusting buckets\$100 pair
Front license plate bracket
• 1939 & 1940 PARTS
1939 NOS Special Carter carburetor (419S)
1939 40 & 60 series wiper transmissions\$200 pair
1939 Jack, used
1940 Jack complete
1940 Jack complete
11949 Oregon Ave. N.
Champlin, MN 55316
(612) 427-3460
(VAM) TEL STOU

Parts WANTED

WANTED:

For 1937 or 1938 Century Series 60 Ring gear and pinion set (with std.ratio 3.9); and propeller shaft. Alternatively the complete rear end. Good condition.

Thank You,

Sverre Christoffersen

E-Mail: sverrech@online.no Mailing address: Nesalleen 30

N-3124 Tonsberg

Norway.

Phone (evening): + 47 33 32 80 93

WANTED FOR 1938 ROADMASTER:

- Rear Axle Ring and Pinion Gear Set (44:11)
 Part no. 1394389
- Rear Brake Drum Part no. 1293550
- Front Brake DrumHub Part no. 1289611
- Delco Front Shock Absorber

Right 1902-D 58 Left 1902-C 58

· Delco-RemyStarter Vacuum Switch

Part no. 1868512

Jari Vuorinen

Mantypolku 5

47710 Jaala

FINLAND

FAX +358 5 3634 508

E-mail: perhe@iobox.fi

Gars FOR SALE

FOR SALE -1938 SPECIAL:

1938 Buick Special, fully restored, in safe | storage, no sidemounts, white-wall tires, | gun-metal silver, original upholstery, under | 50.000 miles

\$8,000.

Jeff Forbes

1307 Hillcrest Dr.

St. Charles, MN 55972

Phone: (507) 932-5649

E-mail: jnlforbes@juno.com

• FOR SALE -1937 CENTURY:

Sport Coupe — Sale or trade, modified, Nova front sub-frame, 1982 Buick V6, Turbo 350 transmission, air conditioning, power steering & windows, 20,000 dependable miles since completion.

\$14,000.

obo or trade for 1947-48-49 sedanette or convertible of equal value.

Greg Marshall (#148)

4800 Meadow Court

New Bern, NC 28562

(252) 635-9052

E-mail: 37buick@always-online.com

FOR SALE -1937 CENTURY:

Trunk-Back 4-Door Sedan Model 61.

"Original." Runs great, new white wall tires. Original interior. Original spare tire, manuals, California plates and amber fog lights. Solid driver

\$8,037.

Steve Nathanson (#656)

Walnut Creek, CA

Phone (925) 947-6711

E-mail: my37buick@aol.com

FOR SALE -1938 SPECIAL:

Model 41 trunk back touring sedan, burgundy, restored all original. Ready to drive or show. Buick National award winner. 70,000 miles. Call between 5-9p.m. CST.

\$13,500.

John Gillio,#1016

15329 Ridgeland

Oak Forest, Illinois 60452

(708) 687-4303

(Cars For Sale continued on page 28)

FOR SALE -1937 CENTURY:

Sport Coupe Model 665 — Black with opera (jump) seats and rear fender skirts, radio and heater. Original condition with 74,000 miles \$16.000.

Rex Borough (#1482)

17426 Dellhaven Ct., Castro Valley, CA 94552

Ph: (510) 582-8075

E-mail: rexborough@home.com





• FOR SALE - 1938 SPECIAL COUPE:

The Car is about 90%. It's missing the parking lights, trunk ornament, plastic map light cover, and little plastic ornaments on door frames. Good tires, new brakes, new battery, almost new mohair interior, rebuilt generator, 17 year old black laquer paint. All else orignal.

\$15,000. obo

Earl L Morey III 20602 Willow Springs Drive Soulsbyville, CA 95372 (209) 533-4531

E-mail: ejmorey@goldrush.com









FOR SALE -1937 LIMITED:

FOR SALE: Series 90 Limo (8 passenger | Sedan w/jumpseats). 85% restored. Only a few parts missing, 95-98% complete. Paint and body work completed, new glass all around, bumpers rechromed, restored steering wheel, hundreds\$\$ in Buick repro or NOS parts for handles, knobs, etc. & much more. Needs interior completed and minor reassembly. Will consider cash offers, or will consider trades of classic convertibles (30's to 50's Buicks or ???) or sports car converts (XKE, Corvette,??). This car is a lifelong Montana car and has had many hours and \$\$\$ put into the restoration so far. Call for more info:

Bruce Barrett 406-542-2595

• PARTS CAR FOR SALE '37-41:

1937 Special 4-Door Sedan Model 41 Has wheels & tires, body, engine, transmission, drive train and radiator. No grille, fenders, hood, trunk lid or interior.

\$200.

Tony Morris San Lorenzo, CA Ph: (510) 487-1706 (work)

FOR SALE -1939 LIMITED:

Dual sidemounts, six new-tires, new motor. The car is in primer and needs a new interior and new wireing.

\$6,000.

Lionel Chartrand Ottawa Valley, Canada (819) 986-2557

Gars WANTED

WANTED - 1937 or 1938:

Convertible Coupe in any condition.

Butch Leonard (#1257)

62777 Erickson Road

Bend, OR 97701

Extra! Extra!

Back Issues Still Available!

The following BACK ISSUES are available for \$4.00 each Postpaid.

- 1991-1992 Volume X Numbers 1 through 9
 - 1992-1993 Volume XI Numbers 6 and 7
- 1993-1994 Volume XII Numbers 2, 4, and 6
 - 1994-1995 Volume XIII Number 6
- 1995-1996 Volume XIV Numbers 3 through 6
 - 1996-1997 Volume XV Number 6
- 1997-1998 Volume XVI Numbers 1 through 6
- 1998-1999 Volume XVII Numbers 1 through 6

Please make your checks payable to:

The 1937-1938 Buick Club, 1005 Rilma Lane, Los Altos, CA 94022 USA

1938 BUICK SPECIALS BY VICTORY MODELS



VL-2 1938 BUICK SPECIAL BUSINESS COUPE

#33

VL-1 1938 BUICK SPECIAL SEDAN

Additional BODY STYLES coming including a TAXI - Also coming soon a 1940 Busck Super - SHIPPING \$6.00 first model, & \$1.00 each additional model end Inquiries and Checks Payable to

RAY PASZKIEWICZ, JR.

P.O. BOX 156, CLARKSBURG, N.J. 08510 TEL. 732-446-9381

FAX 732-446-09297

ONE OF A KIND CAR DISPLAY POSTERS!

Beautiful, Descriptive, Framed Collector Car

DISPLAY POSTERS

for Car Shows are my specialty. These Hand Made Posters really add that "SPECIAL TOUCH" when displayed next to your car. Prices start at \$50.00 and up depending on Color, Size and Rendering of your car. Al Lovi (#994)

ART DESIGN STUDIO 95 Brianne Circle, Windsor, CA 95492 (707) 837-1786

CONVERTIBLE SUN VIS

SUN VISORS Fits 1935-36-37-38-39



\$195.00 each Plus 8% tax for California residence These are authentic visors. All parts are chrome plated.

WALLACE WAMSLEY

(619) 283-3063

4732 Bancroft Street #7, San Diego, California 92116

1904-1965 BUICK RESEARCH SERVICE

More information and detail about your specific 1937 or 1938 Buick year, model and serial number than you can get from any other source. SATISFACTION GUARANTEED. Complete Research Package \$50.00, \$60.00 if shipped outside the USA. Additional information available upon request, or send year, model, serial number, engine number, car photo (if available) and Fisher Body data plate rubbing.

1937 BUICK HIGH QUALITY VIDEO

1937 Buick video made from the only known copy of a 16 mm black & white sound film produced by Buick Motor Division in 1937. The tapes have been made by a professional video dubbing studio. They are very high quality and are produced from a digitally mastered original. Video runs approximately 32 minutes and contains a number of segments showing the construction of the 1937 Buick and Buick's place in American society. Historically significant item. SATISFACTION GUARANTEED. \$39.95 including shipping.



TERRY DUNHAM

AUTOMOTIVE RESEARCH SERVICES



P.O. Box 4057, Apopka, Florida 32704-4057 . Phone 407-880-0797 e-mail: Buickohv@aol.com . web site: www. OldBuickArchive.com

FRONT FLOORMAT 1937-38 All Models Black or Brown FF-378.....\$195.



AUTOMOBILIA (805) 434-2963

1937-38 BUICK



DOOR	WEATHERSEAL-SPONGE

Glue-in	DW-378	\$1.	80	ft.	
Clip-in.	DW-80	\$3.	25	ft.	
	WC-80				
OOR RO	TTOM SEAL				

Clip Type....... DW-369 \$2.25 ft

TRUNK SEAL-SEDANS, 1/2" Wide; Ser. 80-90.......TW-371.....\$35.50

Sedans. 3/4" Wide;

TRUNK SEAL For COUPES. 5/8" x 1" SpongeTL-369\$2.00 ft. 1/2"x1"x16" TL-1129 \$47.50

CLUTCH and BRAKE PEDALS Series 40-60 Black CB-343BK\$5,95 ea. Brown CB-343BN \$5,95 ea.

PEDAL FLOOR SEALS; All ModelsFS-375.....\$12.50 pr.

1937 ONLYI ACCELERATOR PEDALS Series 40-60 Back. AP-37BK \$32.00 Brown...... \$35.50

SHIFT BOOT, 1937-38 Series 40 Only! Black \$ 9.25 Brown.....\$18.50

Series 80-90 Black ONLY.... \$ 8.50 DOOR SILLS: Trim To Fit 2-Door \$62/pr. 4Door \$93/set.

GLOVE BOXES; \$27. ea.

PARKING LIGHT LENS...... \$18.00 ea CARB. KITS:CARTER......CK-360C .\$27.00

STROMBERG...... CK-37XS .\$27.50 TORQUE BALL SEAL KIT. All Models

TBK-343\$27.00 VISOR "VANITY" MIRROR, VM-379 \$27. ea.

LICENSE PLATE FRAMES. Chromed Brass LF-333P.....\$62. Pair

FRONT END PARTS For 40-60 Series: Upper Outer Kit..... \$39.50 King Pin Sets.......\$39.75 Lower Inner Bushings.....\$20.00 Tie Rod End......\$27.00




EXHAUST MANIFOLDS 1937-38 Series 60-80-90 ENDS \$185. CENTER \$189. VALVE BODY \$195.

RUNNING BOARD INSULATORS, 1937-38 All Models. ALL NEW MATERIAL! 4 Needed Per Running Board.

RI-378S Set of 8 .. \$180.00

HOOD REST PADS, 1937-38 6-8 Per Car.

DASH GLASS, SILK-SCREENED on Back of GLASS in COLORS as Original.1937......SPEEDO DG-37 \$38.RADIO.....RG-37.....\$23.CLOCK., CG-37 \$28. 1938...... SPEEDO DG-38 \$38.RADIO.....RG-38.....\$23.CLOCK.. CG-38 \$28.



OUTSIDE DOOR HANDLE CHROME and RUBBER GROMMETS. 1 FERRULE & 1 GROMMET Per Set. 1938...... DGF-380...... \$5./Set



1938 TRUNK HANDLE/LIGHT MOUNTING SEAL \$8.95

MOTOR MOUNT, FRONT. All Models ROUND PADS SP-338 ... \$10. pr. MOUNT......MM-347...\$51. pr

TRUNK HINGES for 40-60. Chrome Plated \$150, pr.

1937 HUB CAPS. All Ser HC-37 \$60. ea. WHEEL Beauty Rings. 15" or 16" \$99./Set of 4 1937 or 38 HOOD ORNAMENT.....\$85.

SOME OTHER ITEMS WE STOCK; BEARINGS, DECALS, ENGINE PAINT, DECALS, SHOP MANUALS, PARTS BOOKS, BODY BOOKS and MORE. SHIPPING:10%. max.\$9. min. \$4. Prepaid. C.O.D. Add \$5.

BOB'S AUTOMOBILIA BOX 2119 ATASCADERO CA. 93423 TELEPHONE (805) 434-2963 .VISA- MASTERCARD-DISCOVER or C.O.D. CATALOG #45 \$5.00 - PHONE ORDERS - (Write For Catalog)

















BUICK...Upholstery and Top Kits 1927/1955

Since 1977 .. Hampton Coach has been producing only the finest quality Interior and Top products available for GM cars. We offer complete interior Kits Scat Upholstery, Tops and related accessories as well as "era" fabric by the yard...

Inquire Toll Free 1-888-388-8726



HAMPTON

6 Chestaut St Tel 978-388-8047

Amesbury, MA Fax 978-388-1113



Restoration and repairs that are correct and authentic.

"I know your Buick."
Former Director of Long
Island, NY Chapter now has
fully equipped shop

in North Georgia. Ron Stanger, BCA #21079

Classic Car Works Ltd., 3050 Upper Bethany Rd. Jasper, GA 30143 Phone (770) 735-3945




J.B. Donaldson Co.

2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505

Beautifully Recast
STEERING WHEELS

Thru 1953 Call or write for brochure



RESTORATION



SERVICES

Running Board / Rocker Moldings

1934 thru 1940

SSAE for Information

BUICK RESTORATION SERVICES

P.O. BOX 442, PERRY,

MICHIGAN

48872



1927

195

WIRING HARNESSES

AUTHENTIC REPRODUCTION
WIRING SYSTEMS THRU 1953
HAND CRAFTED WITH THE
FINEST MATERIALS
EACH SUPPLIED WITH:
LIMITED WARRANTY
INSTALLATION INSTRUCTIONS
SCHEMATICS

ALSO OFFERING: WIRING SUPPLIES CATALOG OR INFORMATION S5



BOX 435 WAYNE, PA. 19087

